## **Installation Guide**

## **1 System Requirements**

XP/Windosw7/Windows10/Windows11

## 2 Hardware Required


- Host: A computer with a 1GHz or faster 32-bit (x86) or 64-bit (x64) processor.
- Memory: 1GB RAM (32-bit) operating system or 2GB RAM (64-bit) operating system.
- Hard disk space: more than 200MB.
- Display: 800×600 resolution.

## **3 Software Installation Procedure**

- 1. Link website https://www.tenmars.com/
- 2. Click English in the upper right corner of the webpage.
- 3. Search TM-4100DN.
- 4. Click on the TM-4100DN photo.
- 5. Click File Download, then select Software Download.
- 6. Download and unzip the software.
- 7. Run autorun.exe, and click to install the following software.

🔮 Temp RH	1 Monitor	×
- (3	TACHO Meter	-
	Software Installation	
	Microsoft .NET Framework	
	<b>USB Driver Installation</b>	
	Installation Guide	
	👽 Exit	

8. Connect this product to a computer with included USB cable.



9. To execute desktop program: double click the program icon to start it.



10. See Software Installation Guide for details on software User Manual.